## **Annexure D**

## **BUILDING SAFETY CERTIFICATE**

No.:.3.8.)	Dated: 09 02 202/					
It is certified that the existing building Narmada Valley International School (name of the						
building or premises) at Near H.P. Petrol Pump, Main Road, Semri Harchand (address) is						
having block(s) / Floor(s) as per details below:						
Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground Floor, First Floor					
The building is owned / occupied by Narmada Valley International School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of						
* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.  Signature with Seal:  Sub-Divisional Office P.W.D. Sub-Dn.No1  rmadapuram (M.P.)  Designation:  The proof of the part of the						